## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,897,553 B2

Page 1 of 3

APPLICATION NO.: 10/633925

**DATED** 

: May 24, 2005

INVENTOR(S)

: Jerrold L. King and Jerry M. Brooks

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page:

In ITEM (75) "Inventors,"

after "Jerrold L. King" change "Boise, ID" to

--Morgan Hill, CA--

In the drawings:

FIG. 5,

delete reference numerals "24A", "24B",

"24C" and the corresponding lead lines

FIG. 7,

change reference numeral "72" to --42--

In the specification:

COLUMN 6,

LINE 45,

change "assemble" to --assembly--

COLUMN 6, LINE 48. change "none conductive" to --nonconductive--

In the claims:

CLAIM 1,

COLUMN 8, LINE 6, change "section" to --sections--

CLAIM 14,

COLUMN 8, LINE 62, change "flip chip" to --flip-chip--

Signed and Sealed this

Sixth Day of January, 2009

JON W. DUDAS Director of the United States Patent and Trademark Office

# UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,897,553 B2

APPLICATION NO. : 10/633925 DATED : May 24, 2005

INVENTOR(S) : Jerrold L. King and Jerry M. Brooks

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Page 2 of 3

#### Replace FIG. 5 with the following:




Fig. 5

# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,897,553 B2 APPLICATION NO. : 10/633925 Page 3 of 3

DATED

).: 10/633925 : May 24, 2005

INVENTOR(S)

: Jerrold L. King and Jerry M. Brooks

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Replace FIG. 7 with the following:

